

2. Brasil Quartz Transparent



Brasil Quartz Transparent analyse chimique: valeurs en %

humidité	Ca O	Mg O	Fe ² O ³	Al ² O ³	SiO ²	MnO	K ² O	Na ² O	TiO	SrO	perte feu
-	0,1	0,11	0,05	0,5	99,12	0,1	0,01	0,09	0,02	0,01	0,16